


June 3, 2008

Dear Sirs;

Please consider this the written request for a hearing before the Water Quality Control Board concerning the WPC case No. WPC08-0121.

- 1) Failed to post the NOC on site. There is no where on this form or the letter with it that states it must be posted. However, it has been posted inside the church at the site.
- 2) SWIPP not Current. The area in question was the path made for the grading equipment to come in and out of the land. It has since been sown and straw spread.
- 3) EPSC measures not in accordance with SWIPP. Pond was only to be temporary. Has been filled according to plan after proper construction completed to prevent damage to area.
- 4) EPSC measures not properly maintained. We are in the process of filing our notice of completion. While there was possibility of damage they were working well.
- 5) Failure to retain sediment on site. Please take note that the inspection also noted that there was no impact to streams or d/s from the site. Therefore the protections in place did their job.

Sincerely,



Leland H. Salyer, Pastor



3266 East Stone Drive Kingsport, TN 37660
(423) 323-3785